



Department of Transport

Repair Design Approval

This approval is issued to:

Pro Aero Aviation Ltd.
2965 Airport Road
Kamloops, British Columbia
Canada V2B 7W8

Number: P-RE92-009

Issue No.: 3

Approval Date: January 10, 1992

Issue Date: January 27, 2015

Responsible Office:

Pacific

Aircraft/Engine Type or Model:

Continental & Lycoming Engine Models with Camshafts
Listed on Continuation sheets

Registration/Serial No.:

Not Applicable

Canadian Type Certificate or Equivalent:

Not Applicable

Description of Type Design Change:

Reconditioning Of Camshafts By Grinding

Installation/Operating Data,
Required Equipment and Limitations:

Camshafts are to be reconditioned in accordance with ProAero Aviation Camshaft Reconditioning
Procedure 12-02, Rev 0, dated 21 January 2015, TCCA approved January 27, 2015*, and applicable
ProAero Engines Inc. Camshaft Grinding Data R001 through R019, Rev. NI, dated January 31, 2007
and TCCA approved January 31, 2007*.

* or later Transport Canada approved revision.

See Continuation Sheet for part number cross reference.

Conditions: This approval is only applicable to the type/model of aeronautical product specified therein.
Prior to incorporating this repair, the installer shall establish that the interrelationship between this repair
and any other modification(s) incorporated will not adversely affect the airworthiness of the modified
product.



Handwritten signature of Robert Metz

Robert Metz
For Minister of Transport